





THREE-PHASE AC MOTOR WINDINGS AND CONNECTIONS





“Y” or star

High voltage




Low voltage




Delta

High voltage



Low voltage



Notes:

1. The most important part of any motor is the nameplate. Check the data given on the plate before making the connections.
2. To change rotation direction of three-phase motor, swap any 2 T-leads.