







THREE-PHASE AC MOTOR WINDINGS AND CONNECTIONS




High voltage




Low voltage



High voltage



Low voltage



- Note:*
1. The most important part of any motor is the nameplate. Check the data given on the plate before making the connections.
 2. To change rotation direction of 3-phase motor, swap any two T-leads.